


# NC150

## laser cutting head

### PRODUCT INSTRUCTION MANUAL



**NC150 high power auto-focus fiber laser cutting head**

**Intelligent Monitoring System**


**Structure and function introduction**

# Contents


1. Product Structure -----	1
1.1 Structure diagram -----	1
2. Installation Size -----	2
3. Basic parameters -----	3
4. Monitoring system -----	4
4.1 Cutting head status display light description -----	4
4.2 Cutting head real-time status interface -----	4
4.3 Monitoring system process mode alarm threshold setting interface -----	5
4.4 Electrical wiring -----	6
4.5 Air pressure correction -----	7

# 1. Product structure

## 1.1 Structure diagram



## 2. Installation size



### 3. Basic parameters

Model: NC150

Max working power:15kw

Collimation focal length:100mm

Focusing focal length:200mm

Focusing adjustment range:±30mm

Centering adjustment range:±1.5mm

Cutting gas pressure:≤2.5Mpa

Fiber types:QBH, QD, Q+, LOE

Weight:≤8.5kg

Gas pipe connector: Cutting gas connector:φ12, Max pressure 25 Bar (2.5Mpa) ;

Nozzle cooling gas connector:φ6, Max pressure 5 Bar (0.5Mpa)


Cooling water connector: φ8, Max pressure 5 Bar (0.5Mpa), water flow: minimum 2.0L/min

Working temperature: -25℃ ~ +55℃

Note: To avoid damage during storage and transport: 1. The cutting head should be stored in the proper temperature and humidity; 2. Avoid vibration and shock; 3. Do not put the cutting head in or near magnetic fields (such as permanent magnets or strong alternating fields).

## 4. Monitoring system

### 4.1 Cutting head status display light description



### 4.2 Cutting head real-time status interface

**NC150 monitoring system**

Process mode: ☐ Air ☒ Oxygen ☐ Nitrogen Gas pressure detection: ☐ Turn off ☒ Turn on

Sensor name	Collimator lens	Focus lens	Upper protective glass	Lower protective glass
Real time values	28.5 °C	29.0 °C	28.7 °C	0.0 °C
Temperature change rate	0.0 °C/S	0.0 °C/S	0.0 °C/S	0.0 °C/S

Cutting gas pressure: 0.14 Bar Gas pressure correction: ☐ Turn off ☒ Turn on Gas pressure calibration

Curve information Gas pressure configuration Details

MAIN CONTROL PAGE SETTING PARAMETERS TEST PAGE

1. Monitor value column: cutting head real-time monitoring status.
2. Alarm value setting column: the default alarm value has been given (to change the alarm value, user needs to click the "Set Parameters" button and enter the permission password to confirm the change.)

### 4.3 Monitoring system process mode alarm threshold setting interface

Sensor name	Change rate shreshold	Overrun prompt threshold	Overrun alarm threshold
Collimator lens	°C/S	°C	°C
Focus lens	°C/S	°C	°C
Upper protective glass	°C/S	°C	°C
Lower protective glass	°C/S	°C	°C
Cutting gas pressure			Bar
Blow-by gas pressure			Bar
Cavity pressure			Bar
Humidity			%
Stray light detection			Ix
Reflective detection			Ix

Buttons at the bottom: Restore factory parameters, Parameter save, Back.

Navigation tabs on the right: MAIN CONTROL PAGE, SETTING PARAMETERS (active), TEST PAGE.

In this interface user can set the process mode related over temperature alarm thresholds and over limit alarm thresholds for the corresponding gases. There are three buttons at the bottom of the function page, which are:


**Restore factory parameters** - Click this button to restore the factory default alarm threshold setting parameters. Note that to use the factory parameters, user needs to click on the parameter save;

**Parameter Save** - Clicking Parameter Save saves the data to the cache, and the power-down data page will not be cleared

**Back**-Return to home page

**Note:** The monitoring parameters can be generally defaulted, and then changed if there are special needs.

#### 4.4 Electrical wiring



1. Cutting head communication interface: used to connect the cutting head and get the cutting head signal parameters;
2. Analog input: The air pressure alarm comparison interface, AD1 and AD- are connected to the analog output port of the board together with A+ and A- of the proportional valve. So that the board outputs 1V to the proportional valve and the monitoring screen page can get the 1V voltage signal for comparison;
3. Reserved signals: two input IO ports, only as reserved;
4. Alarm output: OUT1 and 0V are a set of alarm signals, OUT1 outputs 24V when the cutting head is alarmed, and 3.3V when it is not (the alarm signal is relayed to the board for use);
5. Power supply interface: the 24V3A DC switch power supply is recommended for power supply.



## 4.5 Air pressure correction

Steps:

1. Set open gas pressure to 0.5 on the upper PC and then open;
2. Observe the cutting air pressure at the main interface of the monitoring screen, and record the air pressure of 0.14BAR

The screenshot shows the 'NC150 monitoring system' interface. On the right, a vertical sidebar contains three tabs: 'MAIN CONTROL PAGE' (selected), 'SETTING PARAMETERS', and 'TEST PAGE'. The main area displays the following controls:

- Process mode:** Radio buttons for Air, Oxygen (selected), and Nitrogen.
- Gas pressure detection:** Radio buttons for Turn off and Turn on (selected).
- Sensor data table:**


Sensor name	Collimator lens	Focus lens	Upper protective glass	Lower protective glass
Real time values	28.5 °C	29.0 °C	28.7 °C	0.0 °C
Temperature change rate	0.0 °C/S	0.0 °C/S	0.0 °C/S	0.0 °C/S
- Cutting gas pressure:** A value of 0.14 Bar is displayed.
- Gas pressure correction:** Radio buttons for Turn off and Turn on (selected).
- Buttons:** 'Curve information' (with a graph icon), 'Gas pressure configuration', 'Gas pressure calibration', and 'Details'.

3. Open the test page-analog volume 1 , and record the voltage of 0.5V

The screenshot shows the 'NC150 monitoring system' interface with the 'TEST PAGE' tab selected in the sidebar. The main area is divided into two sections:

- Input -**
  - Radio buttons for Alarm and Back up.
  - Analog 1: 0.50
  - Analog 2: 0.01
- Output -**
  - Radio buttons for General alarm, Gas pressure alarm, Temperature alarm, and Protective window alarm.

4. Return to the home page, click the air pressure correction, fill in the new set of parameters to the first set, and check the enable, click the parameter to save



5. Set the open gas pressure to 1BAR in the upper PC, and then open the gas

6. Repeat steps 2-4 to record the parameters to the second set

7. Continue to increase the air pressure on the upper PC and record five sets of data (the air pressure is set to 0.5BAR -1BAR -1.5BAR -2BAR

-2.5BAR)